



Operating Instructions  
**RS422 Extension terminal,  
EtherCAT**

optoNCDT 1302  
optoNCDT 1402  
optoNCDT 1420  
optoNCDT 1700  
optoNCDT 2200  
optoNCDT 2300

optoCONTROL 2500  
optoCONTROL 2600

RS422 extension terminal

MICRO-EPSILON  
MESSTECHNIK  
GmbH & Co. KG  
Königbacher Straße 15

94496 Ortenburg / Germany

Tel. +49/8542/168-0  
Fax +49/8542/168-90  
email [info@micro-epsilon.de](mailto:info@micro-epsilon.de)  
[www.micro-epsilon.com](http://www.micro-epsilon.com)



EtherCAT® is registered trademark and patented technology,  
licensed by Beckhoff Automation GmbH, Germany.

## Contents

<b>1.</b>	<b>Safety .....</b>	<b>7</b>
1.1	Symbols used .....	7
1.2	Warnings .....	7
1.3	Notes on CE Marking .....	7
1.4	Proper Use .....	8
1.5	Proper Environment .....	8
<b>2.</b>	<b>Functional Principle, Technical Data .....</b>	<b>9</b>
2.1	Functional Principle .....	9
2.2	Technical Data .....	9
2.3	LEDs .....	10
2.4	EtherCAT Port Division .....	10
<b>3.</b>	<b>Delivery .....</b>	<b>11</b>
3.1	Unpacking .....	11
3.2	Storage .....	11
<b>4.</b>	<b>Assembly and Installation .....</b>	<b>11</b>
4.1	Assembly .....	11
4.2	Installation .....	11
<b>5.</b>	<b>Operation .....</b>	<b>13</b>
5.1	EtherCAT Configuration with Beckhoff TwinCAT© Manager .....	13
5.1.1	Slave Information File .....	13
5.1.2	Set Up Interface .....	13
5.1.3	Integrate the RS422 extension terminal .....	14
5.1.4	Configure sensor and system .....	16
5.2	Object Reference .....	19
5.2.1	CoE Object Directory .....	19
5.2.2	Standard Objects .....	19
5.2.3	Sensor objects .....	20
5.2.4	ILD1302 .....	21
	Overview of objects .....	21
	2005 Sensor info .....	21
	2006 Interface settings .....	22
	2050 Get Info .....	22
	2051 Get settings .....	22
	2100 Set Default .....	22
	2101 Reset .....	22
	2132 Laser On .....	22
	2181 Average .....	23
	21A0 Data On .....	23
	21A2 Output Time .....	23
	21A4 RS422 Format .....	23
	21B0 Digital Interfaces .....	23
	2400 Teaching, triggering .....	24
	24A0 Key Lock .....	24
	24C0 Enable Flash .....	24
	24E0 Analog Output Scale .....	24
	24E1 Reset Analog Output scale .....	24
	2502 Set peak searching .....	24
	2550 Set Threshold .....	25
	2999 Sensor Type .....	25
	2FF0 Measurement Value .....	25
	3000 Sensor State .....	25
5.2.5	ILD1402 .....	26
	Overview of objects .....	26
	2005 Sensor info .....	26
	2006 Interface settings .....	27
	2050 Get Info .....	27
	2051 Get settings .....	27
	2100 Set Default .....	27
	2101 Reset .....	27
	2132 Laser On .....	27
	2181 Average .....	28
	21A0 Data On .....	28
	21A1 Output Mode .....	28
	21A2 Output Time .....	28
	21A4 RS422 Format .....	28
	21A5 Hold Last Value .....	28
	21B0 Digital Interfaces .....	29
	2250 Measuring Rate .....	29
	2400 Teaching, triggering .....	29
	24A0 Key Lock .....	29
	24C0 Enable Flash .....	29
	24E0 Analog Output Scale .....	30
	24E1 Reset Analog Output scale .....	30
	2502 Set peak searching .....	30
	2550 Set Threshold .....	30
	2999 Sensor Type .....	30
	2FF0 Measurement Value .....	31

	3000 Sensor State .....	31
5.2.6	ILD1420.....	32
	Overview of objects .....	32
	2001 Login .....	32
	2005 Sensor info .....	33
	2006 Interface settings .....	33
	2020 Basic settings .....	33
	2021 Presets .....	33
	2022 Measurement settings .....	34
	2050 Get Info .....	34
	2100 Set Default .....	34
	2101 Reset.....	34
	2107 Reset Counter.....	34
	2132 Laser On .....	35
	215A Targetmode .....	35
	2161 Peak Position .....	35
	2181 Average.....	35
	21A5 Hold last Value .....	35
	21B0 Digital Interface .....	35
	21E0 Zeroing, Mastering .....	36
	2250 Measuring Rate .....	36
	24A1 Keyfunc.....	36
	24A2 Advanced Keylock .....	36
	2711 Range of Interest .....	36
	2999 Sensor Type.....	36
	2FF0 Measurement Value .....	37
	3000 Sensor State .....	38
5.2.7	ILD1700.....	39
	Overview of objects .....	39
	2005 Sensor info .....	39
	2006 Interface settings .....	40
	2050 Get Info .....	40
	2051 Get settings .....	40
	2100 Set Default .....	40
	2101 Reset.....	40
	2132 Laser On .....	40
	2181 Average.....	41
	21A0 Data On .....	41
	21A4 RS422 Format .....	41
	21A5 Hold Last Value .....	41
	21B0 Digital Interfaces .....	41
	21E0 zeroing, mastering .....	42
	2200 Limit Values.....	42
	2201 Set limits F1 .....	42
	2250 Measuring Rate .....	42
	2400 Synchronize, trigger .....	43
	24A0 Key Lock.....	43
	24C0 Enable Flash for Mastering .....	43
	2999 Sensor Type.....	43
	2FF0 Measurement Value .....	44
	3000 Sensor State .....	44
5.2.8	ILD2200.....	45
	Overview of objects .....	45
	2005 Sensor info .....	45
	2006 Interface settings .....	45
	2050 Get Info .....	46
	2051 Get settings .....	46
	2101 Reset.....	46
	2132 Laser On .....	46
	2181 Average.....	46
	21A0 Data On .....	46
	21E0 zeroing, mastering .....	47
	24A0 Key Lock.....	47
	2999 Sensor Type.....	47
	2FF0 Measurement Value .....	47
	3000 Sensor State .....	48
5.2.9	ILD2300.....	49
	3010 Laser On .....	49
5.2.10	ODC2500 .....	50
	Overview of objects .....	50
	2005 Controller-Info.....	50
	2006 Interface settings .....	51
	2050 Get Info .....	51
	2101 Reset.....	51
	2154 Measuring Program .....	51
	2155 Switch Edge .....	51
	21A0 Data On .....	51
	2600 Edit option data .....	52
	2601 Edit program data .....	52
	2604 Save option data .....	52
	2605 Save program data .....	52
	2606 Read Statistic.....	52
	2607 Reset Statistic .....	52

2999 Sensor Type.....	52
2FF0 Measurement Value .....	53
5.2.11 ODC2600 .....	54
Overview of objects.....	54
2005 Controller-Info.....	54
2006 Interface settings .....	55
2050 Get Info .....	55
2101 Reset.....	55
2130 Set Light Tuning.....	55
2154 Measuring Program.....	55
2155 Switch Edge.....	55
21A0 Data On .....	56
2401 Trigger mode reset .....	56
2402 Trigger Mode Trigger.....	56
2600 Edit option data.....	56
2601 Edit program data.....	56
2604 Save option data .....	56
2605 Save program data.....	56
2606 Read Statistic.....	56
2607 Reset Statistic .....	57
2999 Sensor Type.....	57
2FF0 Measurement Value .....	57
<b>6. Synchronize Sensors .....</b>	<b>58</b>
6.1 Introduction.....	58
6.2 Simultaneous Synchronization.....	58
6.3 Alternating Synchronization .....	61
<b>7. Loading Project in Terminal, Saving.....</b>	<b>66</b>
<b>8. Warranty .....</b>	<b>68</b>
<b>9. Service, Repair .....</b>	<b>68</b>
<b>10. Decommissioning and Disposal.....</b>	<b>68</b>



## 1. Safety

The handling of the system assumes knowledge of the operating instructions.

### 1.1 Symbols used

The following symbols are used in these operating instructions.



Indicates a hazardous situation which, if not avoided, may result in minor or moderate injury.



Indicates a situation that may result in property damage if not avoided.



Indicates a user action.



Indicates a tip for users.

Measure

Indicates hardware or a software button/menu.

### 1.2 Warnings



Connect the electrical components of the RS422 extension terminal only when the terminal is disconnected from the power supply.

> Risk of injury

> Damage to and destruction of the RS422 extension terminal

Connect the power supply in accordance with the safety regulations for electrical equipment.

> Risk of injury

> Damage to and destruction of the RS422 extension terminal

The supply voltage must not exceed the specified limits

> Risk of injury

> Damage to and destruction of the RS422 extension terminal



Avoid shocks and impacts to the RS422 extension terminal.

> Damage to and destruction of the RS422 extension terminal

Connect the sensors/systems only when the RS422 extension terminal is not bearing any voltage.

> Damage to and destruction of the RS422 extension terminal

### 1.3 Notes on CE Marking

The following apply for the RS422 extension terminal:

- EU Directive 2014/30/EU
- EU Directive 2011/65/EU, "RoHS" category 11

Products which carry the CE mark satisfy the requirements of the EU directives cited and the European standards (EN) listed therein. The EU Declaration of Conformity is available to the responsible authorities according to EU Directive, article 10, at:

MICRO-Epsilon Optronic GmbH  
Lessingstraße 14  
01465 Langebrück / Germany

The RS422 extension terminal is designed for use in industrial environments and meets the requirements.

#### **1.4 Proper Use**

- The RS422 extension terminal is designed for industrial use in production automation and machine monitoring. It is used to connect Micro-Epsilon sensors/systems in EtherCAT networks.
- The RS422 extension terminal may only be operated within the limits specified in the technical data, see Chap. [2.2](#).
- The RS422 extension terminal must be used in such a way that no persons are endangered or machines and other material goods are damaged in the event of malfunction or total failure of the RS422 extension terminal.
- Take additional precautions for safety and damage prevention in case of safety-related applications.

#### **1.5 Proper Environment**

- Protection class IP 30
- Operating temperature: 0 ... 50 °C
- Storage temperature: -20 ... +70 °C
- Humidity: 95 %, non-condensing
- Ambient pressure: Atmospheric pressure

## 2. Functional Principle, Technical Data

### 2.1 Functional Principle

The RS422 extension terminal integrates a maximum of 2 Micro-Epsilon sensors/systems in a real-time Ethernet field bus.

Sensors and systems supported:

- optoNCDT 1302
- optoNCDT 1402, 1420
- optoNCDT 1700
- optoNCDT 2200 / optoNCDT 2220
- optoNCDT 2300
- optoCONTROL 2500
- optoCONTROL 2600

Properties:


- Extension terminal for Beckhoff system
- Operation as a slave
- Connection of 2 sensors via RS422 or EtherCAT

The parameters for all inputs and outputs to the RS422 extension terminal and its connected sensors/systems via the Beckhoff TwinCAT® System Manager or other EtherCAT masters. For details, see [www.Bechhoff.com](http://www.Bechhoff.com). etc.

### 2.2 Technical Data


Measuring frequencies	0.312 ... 10 kHz (for RS422) 100 kHz (for EtherCAT)
Baud rates	9600 Baud ... 1.5 MBaud
Connectors	2x push-pull sockets for the sensors
Outputs/inputs:	2x E-bus 2x sensor female connectors, 16-pin (power supply, laser on/off, sync in, RS422, EtherCat) 1x terminal block (Laser On/Off, 24 V, 0V, 2x PE)
Resolution	16 Bit
Conversion time	100 µs
Minimum cycle time per distributed clock	100 µs
Power supply for the electronics	24 VDC ±15%, protected against polarity reversal, supply of the connected sensors via the RS422 extension terminal
Power consumption from the E-Bus	typically 180 mA
Bit width in the process image	Outputs: 2x 16 bit
Configuration	via TwinCAT System Manager
Weight	115 g
Operating temperature	0 °C to 50 °C
Storage temperature	-20 °C to 70 °C
Relative humidity	95%, no condensation
Dimensions	approximately 27 mm x 100 mm x 70 mm (lined up in a row of width: 24 mm)
Installation	on 35 mm mounting rail as per EN 50022
Protection class	IP 30

### 2.3 LEDs



LED	Color	Meaning
L/A	green	Indicate the link status to the sensors.
		off No sensor connected through EtherCAT or no sensor detected through RS422
		on Sensor connected through EtherCAT or sensor detected through RS422
		flashing Sensor connected through EtherCAT and data transmission is on
RUN	green	Indicates the operating state of the terminal.
		off INIT status
		flashing PRE-OP status
		single flash SAFE-OP status
		on OP status

### 2.4 EtherCAT Port Division



### 3. Delivery

#### 3.1 Unpacking

The delivery includes:

- 1 RS422 extension terminal
- 1 assembly Instructions
- 1 spring terminal block
- Carefully remove the components of the measuring system from the packaging and ensure that the goods are forwarded in such a way that no damage can occur.
- Check the delivery for completeness and shipping damage immediately after unpacking.
- If there is damage or parts are missing, immediately contact the manufacturer or supplier.

#### 3.2 Storage

Storage temperature: -20 ... +70 °C


Humidity: 95 % (no condensation)

### 4. Assembly and Installation

- **I** Ensure careful handling during installation and operation. The RS422 extension terminal must be installed when disconnected from the power supply.

#### 4.1 Assembly

- Attach the RS422 extension terminal to a DIN rail, type TS35.
- Observe the minimum bending radii of the connection cables.



*Fig. 1 Dimensional drawing of the RS422 extension terminal, dimensions in mm*

#### 4.2 Installation

Make sure that the individual modules are latched securely into the DIN rail. The bus must be connected with the bus end terminal.

- **I** Connect the sensors/systems only when the RS422 extension terminal is not bearing any voltage.

The sensors/systems connected to the RS422 extension terminal are powered by the field supply.




Fig. 2 Sample configuration of EtherCAT with output and input terminals

**NOTICE**

Damage of extension terminal by balancing current. Connect the extension terminal (PE terminal) to the protective earth connection of mains power.




Fig. 3 Example circuit for the system and field supply


Use separate power supplies for the system supply and field supply.

Do not connect the protective earth connection PE of RS422 extension terminal with the supply ground of system respectively field supply. As a result, the bus communication is disrupted or the RS422 extension terminal damaged.

- Connect the Laser and GND inputs to the RS422 extension terminal in order to switch on the laser beam of the connected sensors, see [Fig. 3](#).

A connection of the input to GND using a button or a transistor (NPN - Open Collector) is sufficient for starting. The laser beam of the sensors that are connected to the RS422 extension terminal is switched off when the inputs are open.

- Connect the EtherCAT bus coupler to a PC. Use a LAN cable with RJ-45 connectors for this.



## 5. Operation

### 5.1 EtherCAT Configuration with Beckhoff TwinCAT® Manager

#### 5.1.1 Slave Information File

The Beckhoff TwinCAT Manager, for example, can be used as EtherCAT® master on the PC.

- Copy the slave information file `RS422klemme_V2.xml` from the enclosed CD to the directory  
 \\TwinCAT\IO\EtherCAT (if TwinCAT® Version  $\leq$  3.0 is used)  
 \\TwinCAT\3.1\IO\EtherCAT (if TwinCAT® Version  $\geq$  3.1 is used).

EtherCAT® slave information files are XML files that specify the properties of the slave device for the EtherCAT® Master and they contain information on the communication objects to be supported. You will find the latest program routine at: [www.micro-epsilon.com/download/software/RS422-klemme-EtherCAT-XML.zip](http://www.micro-epsilon.com/download/software/RS422-klemme-EtherCAT-XML.zip)

- Start the TwinCAT® System Manager program.




Fig. 4 TwinCAT System Manager program interface

#### 5.1.2 Set Up Interface

For the RS422 extension terminal can communicate with the interface card, the driver of the interface card must be replaced by a driver from Beckhoff. Proceed as follows.

- In the TwinCAT menu bar, select the Show Real Time Ethernet Compatible Devices... entry.




Fig. 5 TwinCAT® lists the real time compatible interface cards

- Mark the adapter provided for the connection.

If the driver of the interface card needs an update, the TwinCAT System Manager © enables the **Install** button. If necessary, follow the installation instructions.


If the operating system displays a warning about the "Windows Logo Certification", see illustration below, click on **Continue Anyway**.

- ➡ Click the **Enable** button to complete the installation procedure.


### 5.1.3 Integrate the RS422 extension terminal

- ➡ Select the **Devices** tab, then **Scan**.

- ➡ Confirm with **OK**.




- ➡ Select a network card on which you wish to search for EtherCAT® Slaves.



- ➡ Confirm with **OK**.


The **Scan for boxes (EtherCAT® Slaves)** window will appear.




- ➡ Confirm with **Yes**.

The RS422 extension terminal is now listed in the system configuration.

- ➡ Acknowledge the **Activate free run** window with **Yes**.




- Double-click the Term 2 (CSP2008 Erweiterungsklemme RS422 V2) item and change to the Online tab in the edit window.



The current status on the "online" side should at least indicate "PREOP, SAFEOP or OP". In the event of ERR\_PREOP, the cause will be shown in the message window.

In order to correctly configure the Synchron manager, it is first necessary to read the object directory of the RS422 extension terminal:

- Go to the CoE - Online tab and click the Advanced button.




- Select Offline - from Device Description and All Objects and click on the OK button.  
 ► In the TwinCAT menu, select the Restart TwinCAT (Config Mode) command.


### 5.1.4 Configure sensor and system

The following configuration was performed with a type ILD1420 sensor.

- Select object 2006:01 and set the baud rate for your sensor. Confirm the dialog with OK. The ILD1420 sensor works with a baud rate of 921600 Baud.



- Select Object 2999  
Sensor type and set the sensor used.  
Confirm the dialog with OK. In this example, a sensor of type ILD1420 is used.




► **Select Object 2132**

Laser on and switch on the laser in the sensor. Confirm the dialog with OK.

0 = Laser off

1 = Laser on.



Basic settings are completed by entering the previous baud rate, type of sensor and laser activation objects. Object 3000:01 should have a value of 16 or higher with a proper connection status. Object 2FF0:01 shows measurements.

*Fig. 6 Detail of the CoE-object directory using an ILD1420 sensor*

Index	Name	Flags	Value
2711:0	Range of interest	> 2 <	
2999	Sensor type	RW	ILD1420
2FF0:0	Measurement value	> 7 <	
2FF0:01	Dist	RO	0x8330 (33584)
2FF0:02	Shutter	RO	0x0000 (0)
2FF0:03	Counter	RO	0x0000 (0)
2FF0:04	Timestamp	RO	0x00000000 (0)
2FF0:05	Intensity	RO	0x0000 (0)
2FF0:06	State	RO	0x0000 (0)
2FF0:07	Dist raw	RO	0x0000 (0)
3000:0	Sensor state	> 2 <	
3000:01	Sensor 1	RO	0x11 (17)
3000:02	Sensor 2	RO	0x11 (17)

Repeat the action in objects 4006, 4132 and 4999, if you are running two sensors/systems on the RS422 extension terminal.

## Operation

The PDO assignments can be read from the device on the Process data side:




Fig. 7 Process data of the RS422 extension terminal when programming was finished

► In the TwinCAT menu, select Reload Devices.

The variables Dist and Dist\_1 contain the measurements of the connected sensors.

Configuration is now complete.

Sensor and system	ILD1302	ILD1402	ILD1420	ILD1700	ILD2200	ODC2500	ODC2600	ILD2300		
Interface type, controller	---					RS422		EtherCAT		
Objects RS422 extension terminal										
2006, 4006	Baud rate RS422 exten-	115200	921600	115200	691200					
2999, 4999	Sensor type	ILD	1302	1402	1420	1700	2200	ODC2500		
2132, 4132	Laser on		1	1	1	1	---	---		
21B0: 1, 41B0: 1	Data output sensor/system		1	1	---	2	---	---		

Fig. 8 Summary of elementary object settings

The above illustration, see Fig. 8, illustrates examples of object settings for the individual sensors/systems. The entire object list of the individual sensors/systems, can be found in the object reference.

## 5.2 Object Reference

### 5.2.1 CoE Object Directory

The CoE object directory (CANopen over EtherCAT) contains all a sensor's configuration data, see Fig. 6. The objects in the CoE object directory can be called with the SDO services. Each object is addressed based on a 16-bit index.

### 5.2.2 Standard Objects

#### Overview

Index (h)	Name
1000	Device type
1001	Error register
1008	Device name (manufacturer)
1009	Hardware version
100A	Software version
1018	Identity (device)
1029	Error behavior

#### Object 1000h: Device type

1000	VAR	Device type	0x00000000	Unsigned32	r
------	-----	-------------	------------	------------	---

Supplies information about the device profile and the device type used.

#### Object 1008h: Manufacturer's device name

1008	VAR	Device name	RS422 Kle...	String	r
------	-----	-------------	--------------	--------	---

#### Object 1009h: Hardware version

1009	VAR	Hardware version	HW Vx.x	String	r
------	-----	------------------	---------	--------	---

#### Object 100Ah: Software version

100A	VAR	Software version	SW Vx.x.x	String	r
------	-----	------------------	-----------	--------	---

#### Object 1018h: Device identification

1018	RECORD	Identity	Value	Data type	Access
------	--------	----------	-------	-----------	--------

##### Sub-indices

0	VAR	Number of entries	4	Unsigned8	r
1	VAR	Vendor ID	0x00000607	Unsigned32	r
2	VAR	Product code	0x00000001	Unsigned32	r
3	VAR	Revision number	0x00000001	Unsigned32	r
4	VAR	Serial number	0x00000001	Unsigned32	r

The article number is defined in the product number, the serial number of the sensor is defined in serial number.

### 5.2.3 Sensor objects

An RS422 extension terminal can address a maximum of two sensors. The following object allocation applies:

- Sensor 1: Object 2005h to 2FF0h
- Sensor 2: Object 4005h to 4FF0h

## 5.2.4 ILD1302

### Overview of objects

Index (h)		Name	Description
Sensor 1	Sensor 2		
2005	4005	Sensor info	Sensor information (other)
2006	4006	Interface settings	Baud rate extension terminal
2050	4050	Get info	Query sensor information
2051	4051	Get settings	Selection of the sensor
2100	4100	Set default	Reset to factory setting
2101	4101	Reset	Reboot sensor
2132	4132	Laser on	Switch on laser light source
2181	4181	Average	Averaging setting
21A0	41A0	Data on	Switch measurement output on/off
21A1	41A1	Output mode	Digital/analog data output characteristics
21A2	41A2	Output time	Update digital/analog output value
21A4	41A4	ASCII output	Measurement data format
21B0	41B0	Digital interface	Measurement output and baud rate sensor
2400	4400	Synchronize/trigger	Synchronizing, triggering, operating mode
24A0	44A0	Key lock	Button lock
24C0	44C0	Enable flash for mastering	Release/lock flash writing
24E0	44E0	Analog output scale	Scaling of the analog output
24E1	44E1	Reset analog output scale	Resets analog scaling
2502	4502	Set peak searching	Selection of the peak in the video signal
2550	4550	Set threshold	Video signal search threshold
2999	4999	Sensor type	Specify sensor type
2FF0	4FF0	Measurement value	Reading out the measurements
3000		Sensor state	Connection status

For a description of the individual commands, also see Chapter "Serial interface RS422" in the sensor instructions.

### 2005 Sensor info

#### Object 2005h: Sensor information

2005	RECORD	Sensor info	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	8	Unsigned8	r
1	VAR	Sensor name	ILD1302	String	r
2	VAR	Measuring range	10	String	r
3	VAR	Software version	1.004.1	String	r
4	VAR	Hardware version	1.52	String	r
5	VAR	Serial No.	1012034	String	r
6	VAR	Option no	0	String	r
7	VAR	Calibration date	11/0120	String	r
8	VAR	Article no	4120153	String	r

## 2006 Interface settings

### Object 2006h: Baud rate extension terminal

2006	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	5	Unsigned8	r
1	VAR	Baud rate	115200	Unsigned32	rw

The baud rate in object 2006:01 determines the baud rate of the RS422 extension terminal. The baud rate of the sensor is defined in object 21B0: 02. The two baud rates must match.

## 2050 Get Info

### Object 2050h: Query sensor information

2050	RECORD	Get info	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to retrieve the infostring from the sensor.

## 2051 Get settings

### Object 2051h: Query sensor settings

2051	RECORD	Get settings	Value/parameter	Data type	Access
				Boolean	w

Causes the Terminal to send the GetSettings command to the sensor and to store the received sensor settings in the 2005h objects.

## 2100 Set Default

### Object 2100h: Call up factory setting

2100	RECORD	Set default	Value/parameter	Data type	Access
				Boolean	w

After calling up the factory default, the current output is activated as the output channel in object 21B0:01. Set object 21B0:01 to RS422.

## 2101 Reset

### Object 2101h: Initialize sensor (boot)

2101	RECORD	Reset	Value/parameter	Data type	Access
				Boolean	w

## 2132 Laser On

### Object 2132h: Switch on laser light source

2132	RECORD	Laser on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Laser off

x = 1 : Laser on.

**2181 Average****Object 2181h: Averaging**

2181	RECORD	Average	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Average type	x	Int16	rw
2	VAR	Number of values	y	Int16	rw

X = 0: moving average

Moving average over 1 to 128 measurement

X = 1: Median

median of 3, 5, 7 or 9 measurements

- The averaging type Median requires a valid number of values in the object 2181:02.

**21A0 Data On****Object 21A0h: Switch measurement output on/off**

21A0	RECORD	Data on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Data output off

The output channel (output type) must also be set to the digital output, otherwise the measurement data cannot be received from the sensor.

x = 1 : Data output on

**21A1 Output Mode****Object 21A1h: Digital/analog data output characteristics**

21A1	RECORD	Output mode	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : Continuous

x = 1 : Time-controlled

x = 2 : Triggering

**21A2 Output Time****Object 21A2h: Update digital/analog output value**

21A2	RECORD	Output time	Value/parameter	Data type	Access
			x	Unsigned16	rw

x = 1 ... 65535 [ms]

**21A4 RS422 Format****Object 21A4h: Measurement data format**

21A4	RECORD	RS422 format	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Binary format

x = 1 : ASCII characters

**21B0 Digital Interfaces****Object 21B0h: Measurement output and baud rate sensor**

21B0	RECORD	Digital interfaces	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Output device	x	Unsigned32	rw
2	VAR	Baud rate	y	Unsigned32	rw

x = 0 : Current (4 ... .20 mA)

y = 0 : 115200 Baud

x = 1 : RS422

y = 1 : 57600 Baud

y = 2 : 38400 Baud

y = 3 : 19200 Baud

y = 4 : 9600 Baud

**2400 Teaching, triggering****Object 2400h: Switching input function**

2400	RECORD	Synchronize, trigger	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Operation mode	x	Unsigned8	rw
2	VAR	Reserved			

x = 0 : External input operates as teach conductor

x = 1: External input acts as input for the trigger-controlled data output

**24A0 Key Lock****Object 24A0h: Button lock**

24A0	RECORD	Key lock	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Release button

x = 1 : Button locked

x = 2 : The button is locked automatically 5 minutes after switching on the sensor

**24C0 Enable Flash****Object 24C0h: Release/lock flash writing**

24C0	RECORD	Enable flash	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Store settings in the RAM

x = 1 : Store settings in the FLASH

**24E0 Analog Output Scale****Object 24E0h: Scaling of the analog output**

24E0	RECORD	Analog output scaling	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Start value	x	Float	rw
2	VAR	End value	y	Float	rw

x = 0 : 0.0 to 16368.0

y = 1 : 0.0 to 16368.0

The teaching process requires a valid measuring signal. The teaching process is terminated at „no target“, „target not evaluated“, „to close to the sensor“ - beyond SMR“ or „to far from the sensor - beyond EMR“.

The minimum distance between the scaling values is 10 % of the measuring range.

**24E1 Reset Analog Output scale****Object 24E1: Resets analog scaling**

24E1	RECORD	Reset analog scaling	Value/parameter	Data type	Access
				Boolean	w

**2502 Set peak searching****Object 2502h: Selection of the peak in the video signal**

2502	RECORD	Set peak searching	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : Peak with global maximum

x = 1 : first peak, reading direction pixel 0 to pixel 127, left to right

x = 2 : last peak, reading direction pixel 0 to pixel 127, left to right

## 2550 Set Threshold

### Object 2550h: Video signal search threshold

2550	RECORD	Set threshold	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : Less than standard

x = 1: Standard

x = 2 : higher than standard

x = 3 : highest

## 2999 Sensor Type

### Object 2999h: Specify sensor type

2999	RECORD	Sensor type	Value/parameter	Data type	Access
			ILD1302	String	rw

## 2FF0 Measurement Value

### Object 2FF0h: Reading out the measurements

2FF0	RECORD	Measured value	Value/parameter	Data type	Access
------	--------	----------------	-----------------	-----------	--------

#### Sub-indices

0	VAR	Number of entries	1	Unsigned8	r
1	VAR	Measurement sensor 1		Unsigned16	r

The output values are issued as unsigned digital values (raw values).

Digital value	Use
0 ... 39	Reserve start of measuring range
40 ... 4055	Measuring range
4056 ... 4095	Reserve end of measuring range
16370 ... 16383	Error codes

Calculation of a measurement (in mm)  
from the digital value, reference value  
start of measuring range

$$x [mm] = (\text{digital}_{\text{OUT}} * \frac{1.02}{4096} - 0.01) * \text{MR} [\text{mm}]$$

Example: MB = 10 mm, digital value = 2048, measurement = 5 mm

Digital error codes are output like measurements.

The range of values for error codes: 16370 ... 16384 (digital<sub>OUT</sub>)

16370 No object recognizable

16376 Target cannot be evaluated

16372 too close to the sensor

16380 Target is moving towards sensor

16374 too far from the sensor

16382 Target is moving away from sensor

## 3000 Sensor State

### Object 3000h: Connection status

3000	RECORD	Sensor state	Value/parameter	Data type	Access
------	--------	--------------	-----------------	-----------	--------

#### Sub-indices

0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Unsigned8	r
2	VAR	Sensor 2	x	Unsigned8	r

x = 0 : No RS422 extension terminal

x = 16 : Sensor communication ok

x = 1 : Terminal starts synchronization phase

x = 17 : Measurement reception ok

x = 2 : Terminal in synchronization phase 1

x = 3 : Terminal in synchronization phase 2

x = 4 : Terminal in synchronization phase 3

x = 5 : unknown type of sensor

x = 6 : unknown baud rate

x = 7 : Error during serial initialization

x = 8 : Sensor time-out

## 5.2.5 ILD1402

### Overview of objects

Index (h)		Name	Description
Sensor 1	Sensor 2		
2005	4005	Sensor info	Sensor information (other)
2006	4006	Interface settings	Baud rate extension terminal
2050	4050	Get info	Query sensor information
2051	4051	Get settings	Selection of the sensor
2100	4100	Set default	Reset to factory setting
2101	4101	Reset	Reboot sensor
2132	4132	Laser on	Switch on laser light source
2181	4181	Average	Averaging setting
21A0	41A0	Data on	Switch measurement output on/off
21A1	41A1	Output mode	Digital/analog data output characteristics
21A2	41A2	Output time	Update digital/analog output value
21A4	41A4	ASCII output	Measurement data format
21A5	41A5	Hold last value	Sensor behavior in event of error
21B0	41B0	Digital interface	Measurement output and baud rate sensor
2250	4250	Measuring rate	Measuring rate
2400	4400	Synchronize/trigger	Synchronizing, triggering, operating mode
24A0	44A0	Key lock	Button lock
24C0	44C0	Enable flash for mastering	Release/lock flash writing
24E0	44E0	Analog output scale	Scaling of the analog output
24E1	44E1	Reset analog output scale	Resets analog scaling
2502	4502	Set peak searching	Selection of the peak in the video signal
2550	4550	Set threshold	Video signal search threshold
2999	4999	Sensor type	Specify sensor type
2FF0	4FF0	Measurement value	Reading out the measurements
3000		Sensor state	Connection status

For a description of the individual commands, also see Chapter "Serial interface RS422" in the sensor instructions.

### 2005 Sensor info

#### Object 2005h: Sensor information

2005	RECORD	Sensor info	Value/parameter	Data type	Access
------	--------	-------------	-----------------	-----------	--------

#### Sub-indices

0	VAR	Number of entries	8	Unsigned8	r
1	VAR	Sensor name	ILD1402	String	r
2	VAR	Measuring range	10	String	r
3	VAR	Software version	1.004.1	String	r
4	VAR	Hardware version	1.52	String	r
5	VAR	Serial No.	1012054	String	r
6	VAR	Option no	0	String	r
7	VAR	Calibration date	11/01/20	String	r
8	VAR	Article no	4120152	String	r

## 2006 Interface settings

### Object 2006h: Baud rate extension terminal

2006	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	5	Unsigned8	r
1	VAR	Baud rate	115200	Unsigned32	rw

The baud rate in object 2006:01 determines the baud rate of the RS422 extension terminal. The baud rate of the sensor is defined in object 21B0: 02. The two baud rates must match.

## 2050 Get Info

### Object 2050h: Query sensor information

2050	RECORD	Get info	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to retrieve the infostring from the sensor.

## 2051 Get settings

### Object 2051h: Query sensor settings

2051	RECORD	Get settings	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to send the GetSettings command to the sensor and to store the received sensor settings in the 2005h objects.

## 2100 Set Default

### Object 2100h: Call up factory setting

2100	RECORD	Set default	Value/parameter	Data type	Access
				Boolean	w

After calling up the factory default the current output is activated as the output channel in object 21B0:01. Set object 21B0:01 to RS422.

## 2101 Reset

### Object 2101h: Initialize sensor (boot)

2101	RECORD	Reset	Value/parameter	Data type	Access
				Boolean	w

## 2132 Laser On

### Object 2132h: Switch on laser light source

2132	RECORD	Laser on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Laser off

x = 1 : Laser on.

**2181 Average****Object 2181h: Averaging**

2181	RECORD	Average	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Average type	x	Int16	rw
2	VAR	Number of values	y	Int16	rw

X = 0: moving average

Moving average over 1 to 128 measurement values

X = 1: Median

Median of 3, 5, 7 or 9 measurements

- The averaging type Median requires a valid number of values in the object 2181:02.
- i

**21A0 Data On****Object 21A0h: Switch measurement output on/off**

21A0	RECORD	Data on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Data output off

x = 1 : Data output on

The output channel (output type) must also be set to the digital output, otherwise the measurement data cannot be received from the sensor.

**21A1 Output Mode****Object 21A1h: Digital/analog data output characteristics**

21A1	RECORD	Output mode	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : Continuous

x = 1 : Time-controlled

x = 2 : Triggering

**21A2 Output Time****Object 21A2h: Update digital/analog output value**

21A2	RECORD	Output time	Value/parameter	Data type	Access
			x	Unsigned16	rw

x = 1 ... 65535 [ms]

**21A4 RS422 Format****Object 21A4h: Measurement data format**

21A4	RECORD	RS422 format	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Binary format

x = 1 : ASCII characters

**21A5 Hold Last Value****Object 21A5h: Retain measurement**

21A5	RECORD	Hold last value	Value/parameter	Data type	Access
			x	Unsigned8	rw

x = 0 : Hold last measurement

x = 1 : Output error signal

x = 2 ... 99 : Hold last measurement for 2 ... 99 images or measuring cycles

The command only affects the analog output.

## 21B0 Digital Interfaces

### Object 21B0h: Measurement output and baud rate sensor

21B0	RECORD	Digital interfaces	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Output device	x	Unsigned32	rw
2	VAR	Baud rate	y	Unsigned32	rw

x = 0 : Current (4 .. .20 mA)

y = 0 : 115200 Baud

x = 1 : RS422

y = 1 : 57600 Baud

y = 2 : 38400 Baud

y = 3 : 19200 Baud

y = 4 : 9600 Baud

## 2250 Measuring Rate

### Object 2250h: Set measuring rate

2250	RECORD	Measuring rate	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Reserved			
2	VAR	Measuring rate	x	Int8	rw

x = 0 : 1.5 kHz

x = 1 : 1.0 kHz

x = 2 : 750 Hz

x = 3 : 375 Hz

x = 4 : 50 Hz

## 2400 Teaching, triggering

### Object 2400h: Switching input function

2400	RECORD	Synchronize, trigger	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Operation mode	x	Unsigned8	rw
2	VAR	Reserved			

x = 0 : External input operates as teach conductor

x = 1 : External input acts as input for the trigger-controlled data output

## 24A0 Key Lock

### Object 24A0h: Button lock

24A0	RECORD	Key lock	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Release button

x = 1 : Button locked

x = 2 : The button is locked automatically 5 minutes after switching on the sensor

## 24C0 Enable Flash

### Object 24C0h: Release/lock flash writing

24C0	RECORD	Enable flash	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Store settings in the RAM

x = 1 : Store settings in the FLASH

**24E0 Analog Output Scale****Object 24E0h: Scaling of the analog output**

24E0	RECORD	Analog output scaling	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Start value	x	Float	rw
2	VAR	End value	y	Float	rw

x = 0 : 0.0 to 16368.0

y = 1 : 0.0 to 16368.0

The teaching process requires a valid measuring signal. The teaching process is terminated at „no target“, „target not evaluated“, „to close to the sensor“ - beyond SMR“ or „to far from the sensor - beyond EMR“.

The minimum distance between the scaling values is 10 % of the measuring range.

**24E1 Reset Analog Output scale****Objekt 24E1: Resets analog scaling**

24E1	RECORD	Reset analog scaling	Value/parameter	Data type	Access
				Boolean	w

**2502 Set peak searching****Object 2502h: Selection of the peak in the video signal**

2502	RECORD	Set peak searching	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : Peak with global maximum

x = 1 : first peak, reading direction pixel 0 to pixel 127, left to right

x = 2 : last peak, reading direction pixel 0 to pixel 127, left to right

**2550 Set Threshold****Object 2550h: Video signal search threshold**

2550	RECORD	Set threshold	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : Less than standard

x = 1 : Standard

x = 2 : higher than standard

x = 3 : highest

**2999 Sensor Type****Object 2999h: Specify sensor type**

2999	RECORD	Sensor type	Value/parameter	Data type	Access
			ILD1402	String	rw

## 2FF0 Measurement Value

### Object 2FF0h: Reading out the measurements

2FF0	RECORD	Measured value	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	1	Unsigned8	r
1	VAR	Measurement sensor 1		Unsigned16	r

The output values are issued as unsigned digital values (raw values).

Digital value	Use
0 ... 39	Reserve measuring range start
40 ... 4055	Drawings
4056 ... 4095	Reserve measuring range end
16370 ... 16383	Error codes

Calculation of a measurement (in mm)  
from the digital value, reference value  
start of measuring range

$$x \text{ [mm]} = (\text{digital}_{\text{OUT}} * \frac{1.02}{16368} - 0.01) * \text{MR} \text{ [mm]}$$

Example: MR = 10 mm, digital value = 8184, measurement = 5 mm

Digital error codes are output like measurements.

The range of values for error codes: 16370 ... 16384 (digital<sub>OUT</sub>)

16370	No object recognizable	16376	Target cannot be evaluated
16372	too close to the sensor	16380	Target is moving towards sensor
16374	too far from the sensor	16382	Target is moving away from sensor

## 3000 Sensor State

### Object 3000h: Connection status

3000	RECORD	Sensor state	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Unsigned8	r
2	VAR	Sensor 2	x	Unsigned8	r

- x = 0 : No RS422 extension terminal
- x = 1 : Terminal starts synchronization phase
- x = 2 : Terminal in synchronization phase 1
- x = 3 : Terminal in synchronization phase 2
- x = 4 : Terminal in synchronization phase 3
- x = 5 : unknown type of sensor
- x = 6 : unknown baud rate
- x = 7 : Error during serial initialization
- x = 8 : Sensor timeout
- x = 16 : Sensor communication ok
- x = 17 : Measurement reception ok

## 5.2.6 ILD1420

### Overview of objects

Index (h)		Name	Description
Sensor 1	Sensor 2		
2001	4001	Login	User level
2005	4005	Sensor info	Sensor information (other)
2006	4006	Interface settings	Baud rate extension terminal
2020	4020	Basic settings	Load/store device settings
2021	4021	Presets	Load preset
2022	4022	Measurement settings	Load/store measurement settings
2050	4050	Get info	Query sensor information
2100	4100	Set default	Reset to factory setting
2101	4101	Reset	Reboot sensor
2107	4107	Reset counter	Reset measurement counter
2132	4132	Laser on	Switch on laser light source
215A	415A	Targetmode	Select measurement mode
2161	4181	Peak position	Peak selection in the video signal
2181	4181	Averaging	Measurement averaging
21A5	41A5	Hold last value	Behavior of the analog output
21B0	41B0	Digital interface	Baud rate sensor
21E0	41E0	Zeroing, mastering	Set output to zero or master value
2250	4250	Measuring rate	Measurement frequency
24A1	42A1	Keyfunc	Key function
24A2	42A2	Advanced keylock	Activate/lock key
2711	4711	Range of interest	Evaluation range
2999	4999	Sensor type	Specify sensor type
2FF0	4FF0	Measurement value	Reading out the measurements
3000		Sensor state	Connection status

For a description of the individual commands, also see Chapter "Serial interface RS422" in the sensor instructions.

### 2001 Login

#### Object 2001h: Login

2001	RECORD	Login	Value/parameter	Data type	Access
------	--------	-------	-----------------	-----------	--------

#### Sub-indices

0	VAR	Anzahl Einträge	4	Unsigned8	ro
1	VAR	Actual user	x	Unsigned8	ro
2	VAR	Login	*****	String	wo
3	VAR	Logout	FALSE	BOOL	wo
4	VAR	Default user	x	Unsigned8	rw

## 2005 Sensor info

### Object 2005h: Sensor information (other)

2005	RECORD	Sensor info	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	8	Unsigned8	r
1	VAR	Sensor name	ILD1420	String	r
2	VAR	Measuring range	10.00mm	String	r
3	VAR	Software version	xxx.xx	String	r
4	VAR	Hardware version	xxx	String	r
5	VAR	Serial No.	xxxxxxxx	String	r
6	VAR	Option no	0xx	String	r
7	VAR	Calibration date		String	r
8	VAR	Article no	4120212	String	r

## 2006 Interface settings

### Object 2006h: Baud rate extension terminal

2006	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	5	Unsigned8	r
1	VAR	Baud rate	921600	Unsigned32	rw

The baud rate in object 2006:01 determines the baud rate of the RS422 extension terminal. The baud rate of the sensor is defined in object 21B0: 02. The two baud rates must match.

## 2020 Basic settings

### Object 2020h: Device settings

2020	RECORD	Basic settings	Value/Parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	3	Unsigned8	ro
1	VAR	Read		BOOL	wo
2	VAR	Store		BOOL	wo
3	VAR	Set default		BOOL	wo

- Read: Loads the stored device settings.
- Store: Saves the current device settings.
- Set default: Resets the device settings on factory setting.

## 2021 Presets

### Objekt 2021h: Load presets

2021	RECORD	Presets	Value/Parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	3	Unsigned8	ro
1	VAR	Mode	x	Unsigned8	rw
2	VAR	List		String	ro
3	VAR	Named read		String	wo

x = 0 : STATIC  
x = 1 : BALANCED  
x = 2 : DYNAMIC

- List: Listing of all saved measurement settings, see object 2022.
- Named read: Loads a measurement setting from „List“ / sub-indice 2, see object 2022.

**2022 Measurement settings****Object 2022h: Messeinstellungen laden/speichern**

2022	RECORD	Meassettings	Value/parameter	Data type3	Access
Sub-indices					
0	VAR	Number of entries	7	Unsigned8	ro
1	VAR	Current		String	ro
2	VAR	Named read		String	wo
3	VAR	Named store		String	wo
4	VAR	Named delete		String	wo
5	VAR	Initial meassettings		String	rw
6	VAR	List		String	ro
7	VAR	Set default		BOOL	wo

- Current: contains the current measurement settings (MEASSETTINGS CURRENT).
- Named read: Loads a measurement setting from „List“ / sub-indice 6, (MEASSETTINGS READ).
- Named store: Saves the current measurement setting. Assign a name or a number (MEASSETTINGS STORE).
- Named delete: Deletes a measurement setting from „List“ / sub-indice 6, (MEASSETTINGS DELETE).
- Initial meassettings: Measurement setting, which is loaded first at a reset of the sensor (MEASSETTINGS INITIAL).
- List: Listing of all saved measurement settings (MEASSETTINGS LIST).
- Set default: Corresponds to the SETDEFAULT MEASSETTINGS command.

**2050 Get Info****Object 2050h: Query sensor information**

2050	RECORD	Get info	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to retrieve the infostring from the sensor.

**2100 Set Default****Object 2100h: Call up factory setting**

2100	RECORD	Set default	Value/parameter	Data type	Access
				Boolean	w

Resets the sensor on factory setting.

**2101 Reset****Object 2101h: Initialize sensor (boot)**

2101	RECORD	Reset	Value/parameter	Data type	Access
				Boolean	w

**2107 Reset Counter****Object 2107h: Reset counter**

2107	RECORD	Reset Counter	Value/parameter	Data type	Access
Sub-indice					

0	VAR	Number of entries	2	Unsigned8	ro
1	VAR	Reset counter	x	Bool	wo
2	VAR	Reset meas counter	x	Bool	wo

**2132 Laser On****Object 2132h: Switch on laser light source**

2132	RECORD	Laser on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Laser off

x = 1 : Laser on

**215A Targetmode****Object 215Ah: Measurement mode**

215A	RECORD	Targetmode	Value/parameter	Data type	Access
			x	Unsigned16	rw

x = 0 : Standard, suitable for materials, e.g. made of ceramics, metal, plastics or wood

x = 1 : Multisurface, suitable for materials with changing surfaces, e.g. PCB or hybrid materials

x = 2 : Penetration, suitable for materials with strong penetration depth of the laser light

**2161 Peak Position****Object 2161h: Peak selection in the vide osignal**

2161	RECORD	Peak position	Value/parameter	Data type	Access
			x	Unsigned8	rw

x = 0 : DISTA, output of peak with highest amplitude (standard)

x = 1 : DIST1, output of first peak

x = 2 : DISTL, output of last peak

**2181 Average****Object 2181h: Averaging**

2181	RECORD	Average	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	2	Unsigned8	ro
1	VAR	Average type	x	Signed8	rw
2	VAR	Number of values	y	Unsigned16	rw

x = 0 : keine Mittelung

y

x = 1 : gleitend moving average over 2 / 4 / 8 to 128 measurements

x = 2 : Rekursiv recursive average over 1 to 32768 measurements

x = 3 : Median median of 3, 5, 7 or 9 measurements

**21A5 Hold last Value****Object 21A5h: Error handling**

21A5	RECORD	Hold last value	Value/parameter	Data type	Access
			x	Unsigned16	rw

x = 0 : Output error signal

x = 1 : Hold last measurement

**21B0 Digital Interface****Object 21B0h: Baud rate sensor**

21B0	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	2	Unsigned8	ro
2	VAR	Baudrate	x	Unsigned32	rw

x = 9600|19200|56000|115200|128000|230400|256000|460800|691200|921600|

1000000 Baud

The baud rate in object 21B0:02 determines the baud rate of the sensor. The baud rate of the RS422 extension terminal is defined in object 2006: 01. The two baud rates must match.

**21E0 Zeroing, Mastering****Object 21E0h: Zeroing, mastering**

21E0	RECORD	Zeroing, mastering	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	4	Unsigned8	ro
1	VAR	Reserved			
2	VAR	Master value		Int16	rw
3	VAR	Zeroing/mastering active	x	Bool	ro
4	VAR	Mastering/reset mastering	y	Bool	wo

x = 0 : Setting of masters and mid-point cancelled

x = 1 : Master value/mid-point set

y = 0 : Cancel setting of master value and mid-point

y = 1 : Setting master value and the mid-point

**2250 Measuring Rate****Object 2250h: Measuring rate**

2250	RECORD	Measuring rate	Value/parameter	Data type	Access
Sub indices					
0	VAR	Number of entries	5	Unsigned8	ro
5	VAR	Manual measuring rate	x	float	rw

x = 0.250, 0.500, 1, 2 or 4 kHz

**24A1 Keyfunc****Object 24A1h: key function**

24A1	RECORD	Keyfunc	Value/parameter	Data type	Access
			x	Unsigned16	rw

x = 0 : none

x = 2 : Teaching

x = 1 : Mastering

**24A2 Advanced Keylock****Object 24A2h: Advanced keylock**

24A2	RECORD	Advanced keylock	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	ro
1	VAR	Mode	x	Unsigned8	rw
2	VAR	Delay	y	Unsigned16	rw

x = 0 : none

y = 0 ... 60 [min]

x = 1 : active

x = 2 : automatic

**2711 Range of Interest****Object 2711h: Evaluation range**

2711	RECORD	Range of interest	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	ro
1	VAR	Start of range		Unsigned16	rw
2	VAR	End of range		Unsigned16	rw

**2999 Sensor Type****Object 2999h: Specify sensor type**

2999	RECORD	Sensor type	Value/parameter	Data type	Access
			ILD1420	String	rw

**2FF0 Measurement Value****Object 2FF0h: Reading out the measurements**

2FF0	RECORD	Measurement value	Value/parameter	Data type	Access
------	--------	-------------------	-----------------	-----------	--------

## Sub-indexes

0	VAR	Number of entries	7	Unsigned8	ro
1	VAR	Dist		Unsigned16	ro
2	VAR	Shutter		Unsigned16	ro
3	VAR	Counter		Unsigned16	ro
4	VAR	Timestamp		Unsigned32	ro
5	VAR	Intensity		Unsigned16	ro
6	VAR	State		Unsigned16	ro
7	VAR	Dist raw		Unsigned16	ro

The output values are issued as unsigned digital values (raw values). 16 resp. 18 bits per value are being transmitted. Subsequently you can find a compilation of output values and the conversion of the digital value.

Value	Length	Variables	Value range	Formula
Distance (without master-ing)	16 bits	x = digital value  MR = measuring range [mm]  d = distance [mm]	[0; <643] SMR reserve [643; 64877] measuring range [>64877; 65520] EMR reserve  {10/25/50}  [-0,01MR; 1,01MR]	$d \text{ [mm]} = \frac{1}{100} \left( \frac{102}{65520} x - 1 \right) * MR \text{ [mm]}$
Distance (with master-ing)	18 bits	x = digital value  MR = measuring range [mm]  MP = master position [mm]  MV = master value [mm]  d = distance [mm]	{10/25/50}  [0; MR]  [0; 2MR]  [-0.5MR + MV; MR - MP + MV]  [-MP + MV; MR - MP + MV]	The output range is also coded with 64235 values at 18 bit and shifted with the master value. The reserves at SMR and EMR are coded with 643 values each.  $d \text{ [mm]} = \frac{1}{100} \left( \frac{102}{65520} x - 51 \right) * MR \text{ [mm]}$
Exposure time	18 bits	x = digital value  ET = exposure time [ $\mu$ s]	[1; 262143]  [0.1; 26214.3]	$ET \text{ [\mu s]} = \frac{1}{10} x$
Intensity	16 bits	x = digital value  I = intensity [%]	[0; 65472]  [0; 100]	$I \text{ [%]} = \frac{25}{16368} x$
Sensor status	18 bits	x = digital value  Bit encoding  SMR = Start of measuring range EMR = End of measuring range	[0; 242143]  [0; 1]  Bit 0 (LSB): peak starts before ROI Bit 1: peak ends after ROI Bit 2: no peak found Bit 5: distance before SMR (extended) Bit 6: distance after EMR (extended) Bit 15: measuring value is triggered Bit 16, 17: status LED; - 00 – off      10 – red - 01 – green    11 – yellow	
Measurement counter	18 bits	x = digital value	[0; 262143]	

Time stamp	2 words, at 16 bit	x = digital value Lo y = digital value Hi	[0; 65535] [0; 65535]	$t \text{ [ms]} = \frac{1}{100} (65536y + x)$
		t = time stamp [ms]	[0; 11h55m49.67s]	
Non-linear- ized focus	18 bits	x = digital value	[0; 262143]	$NF \text{ [%]} = \frac{100}{262143} \times$
		NF = focus	[0; 100]	
Video raw signal	16 bits	512 pixel	[0; 65535]	

Additional information transmitted in the distance value

Distance value	Description
262075	data amount to big for selected baud rate
262076	no peak available
262077	peak before the measurement range (MR)
262078	peak behind the measurement range (MR)
262080	measurement value can not be calculated
262081	peak is to large
262082	Laser is off

### 3000 Sensor State

#### Object 3000h: Connection status

3000	RECORD	Sensor state	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Unsigned8	r
2	VAR	Sensor 2	x	Unsigned8	r

- x = 0 : No RS422 extension terminal
- x = 1 : Terminal starts synchronization phase
- x = 2 : Terminal in synchronization phase 1
- x = 3 : Terminal in synchronization phase 2
- x = 4 : Terminal in synchronization phase 3
- x = 5 : unknown type of sensor
- x = 6 : unknown baud rate
- x = 7 : Error during serial initialization
- x = 8 : Sensor timeout
- x = 16 : Sensor communication ok
- x = 17 : Measurement reception ok

### 5.2.7 ILD1700

#### Overview of objects

Index (h)		Name	Description
Sensor 1	Sensor 2		
2005	4005	Sensor info	Sensor information (other)
2006	4006	Interface settings	Baud rate extension terminal
2050	4050	Get info	Query sensor information
2051	4051	Get settings	Selection of the sensor
2100	4100	Set default	Reset to factory setting
2101	4101	Reset	Reboot sensor
2132	4132	Laser on	Switch on laser light source
2181	4181	Average	Averaging setting
21A0	41A0	Data on	Switch measurement output on/off
21A4	41A4	ASCII output	Measurement data format
21A5	41A5	Hold last value	Sensor behavior in event of error
21B0	41B0	Digital interface	Measurement output and baud rate sensor
21E0	41E0	Zeroing	Setting masters and the mid-point
2200	4200	Set limits	Set limit values
2201	4201	Set limits F1	Assign switch outputs
2250	4250	Measuring rate	Measuring rate
2400	4400	Synchronize/trigger	Synchronizing, triggering, operating mode
24A0	44A0	Key lock	Button lock
24C0	44C0	Enable flash for mastering	Release/lock flash writing
2999	4999	Sensor type	Specify sensor type
2FF0	4FF0	Measurement value	Reading out the measurements
3000		Sensor state	Connection status

For a description of the individual commands, also see Chapter "RS422 serial port" in the sensor instructions.

#### 2005 Sensor info

##### Object 2005h: Sensor information

2005	RECORD	Sensor info	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	8	Unsigned8	r
1	VAR	Sensor name	ILD1700	String	r
2	VAR	Measuring range	200	String	r
3	VAR	Software version	5,047	String	r
4	VAR	Hardware version	1.52	String	r
5	VAR	Serial No.	706102	String	r
6	VAR	Option no	0	String	r
7	VAR	Calibration date	11/10/20	String	r
8	VAR	Article no	4120092	String	r

## 2006 Interface settings

### Object 2006h: Baud rate extension terminal

2006	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	5	Unsigned8	r
1	VAR	Baud rate	115200	Unsigned32	rw

The baud rate in object 2006:01 determines the baud rate of the RS422 extension terminal. The baud rate of the sensor is defined in object 21B0: 02. The two baud rates must match.

## 2050 Get Info

### Object 2050h: Query sensor information

2050	RECORD	Get info	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to retrieve the infostring from the sensor.

## 2051 Get settings

### Object 2051h: Query sensor settings

2051	RECORD	Get settings	Value/parameter	Data type	Access
				Boolean	w

Causes the Terminal to send the GetSettings command to the sensor and to store the received sensor settings in the 2005h objects.

## 2100 Set Default

### Object 2100h: Call up factory setting

2100	RECORD	Set default	Value/parameter	Data type	Access
				Boolean	w

After calling up the factory default the current output is activated as the output channel in object 21B0:01. Set object 21B0:01 on RS422, see Object 21B0.

## 2101 Reset

### Object 2101h: Initialize sensor (boot)

2101	RECORD	Reset	Value/parameter	Data type	Access
				Boolean	w

## 2132 Laser On

### Object 2132h: Switch on laser light source

2132	RECORD	Laser on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Laser off

x = 1 : Laser on.

**2181 Average****Object 2181h: Averaging**

2181	RECORD	Average	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Average type	x	Int16	rw
2	VAR	Number of values	y	Int16	rw

x = 0 : recursive average  
 Recursive average of 1 to 32768 measurements  
 x = 1 : moving average  
 moving average of 1 to 128 measurements  
 x = 2 : Median  
 median of 3, 5, 7 or 9 measurements

The averaging number applies only for the moving and the recursive average.

Averaging number	1	2	4	8	16	32	64	128	256	512	1024	2048	4096
y	0	1	2	3	4	5	6	7	8	9	10	11	12
Averaging number	8192 16384 32768												
y	13	14	15										

**21A0 Data On****Object 21A0h: Switch measurement output on/off**

21A0	RECORD	Data on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Data output off  
 x = 1 : Data output on

**21A4 RS422 Format****Object 21A4h: Measurement data format**

21A4	RECORD	RS422 format	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Binary format  
 x = 1 : ASCII characters

**21A5 Hold Last Value****Object 21A5h: Retain measurement**

21A5	RECORD	Hold last value	Value/parameter	Data type	Access
			x	Unsigned8	rw

x = 0 : Output error signal  
 x = 1 : Hold last measurement

The command only affects the analog output.

**21B0 Digital Interfaces****Object 21B0h: Measurement output and baud rate sensor**

21B0	RECORD	Digital interfaces	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Output device	x	Unsigned32	rw
2	VAR	Baud rate	y	Unsigned32	rw

x = 0 : Current (4 ... .20 mA)  
 y = 0 : 115200 Baud  
 x = 1 : voltage (0 ... 10 V)  
 y = 1 : 57600 Baud  
 x = 2 : RS422  
 y = 2 : 19200 Baud  
 y = 3 : 9600 Baud

**21E0 zeroing, mastering****Object 21E0h: Zeroing, mastering/**

21E0	RECORD	Zeroing, mastering	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	4	Unsigned8	r
1	VAR	Reserved			
2	VAR	Master value		Int16	rw
3	VAR	Zeroing/mastering active	x	Boolean	r
4	VAR	Mastering/reset mastering	y	Boolean	w

x = 0 : Setting of masters and mid-point cancelled  
x = 1 : Masters/mid-point set

y = 0 : Cancel setting of masters and mid-point  
y = 1 : Setting masters and the mid-point

**2200 Limit Values****Object 2200h: Set limit values**

2200	RECORD	Limit values	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	4	Unsigned8	r
1	VAR	Upper limit		Int16	rw
2	VAR	Lower limit		Int16	rw
3	VAR	Upper hysteresis		Int16	rw
4	VAR	Lower hysteresis		Int16	rw

**2201 Set limits F1****Object 2201h: Assign switch outputs**

2201	RECORD	Set limits F1	Value/parameter	Data type	Access
			x	Int16	rw

x = 0 : Upper limit switch output 2, lower limit switch output 1  
x = 1 : Upper limit switch output 1, lower limit switch output 2

**2250 Measuring Rate****Object 2250h: Set measuring rate**

2250	RECORD	Measuring rate	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Reserved			
2	VAR	Measuring rate	x	Int8	rw

x = 0 : 2.5 kHz  
x = 1 : 1.25 kHz  
x = 2 : 625 Hz  
x = 3 : 312.5 Hz

**2400 Synchronize, trigger****Object 2400h: Synchronizing, triggering, operating mode**

2400	RECORD	Synchronize, trigger	Value/parameter	Data type	Access
------	--------	----------------------	-----------------	-----------	--------

## Sub-indices

0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Operation mode	x	Unsigned8	rw
2	VAR	Synchronous/trigger	y	Unsigned8	rw

x = 0 : Sync/error  
 x = 1 : Sync/switch  
 x = 2 : Trigger/error  
 x = 3 : Trigger/switch

for x = 0/1  
 y = 0 : Master synchronous off  
 y = 1 : Master synchronous on  
 y = 2 : Slave  
 y = 3 : Master synchronous alternating

For x = 2/3  
 y = 0 : Flank positive  
 y = 1 : Flank negative  
 y = 2 > level high  
 y = 3 > level low

**24A0 Key Lock****Object 24A0h: Button lock**

24A0	RECORD	Key lock	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Unlock keyboard  
 x = 1 : Keyboard locked

**24C0 Enable Flash for Mastering****Object 24C0h: Release/lock flash writing**

24C0	RECORD	Enable flash mastering	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Flash writing locked  
 x = 1 : Flash writing released

**2999 Sensor Type****Object 2999h: Specify sensor type**

2999	RECORD	Sensor type	Value/parameter	Data type	Access
			ILD1700	String	rw

## 2FF0 Measurement Value

### Object 2FF0h: Reading out the measurements

2FF0	RECORD	Measured value	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	1	Unsigned8	r
1	VAR	Measurement sensor 1		Unsigned16	r

The output values are issued as unsigned digital values (raw values).

Digital value	Use
0 ... 160	Reserve measuring range start
161 ... 16207	Drawings
16208 ... 16367	Reserve measuring range end
16370 ... 16383	Error codes

Calculation of a measurement (in mm) from the digital value, reference value start of measuring range

$$x [\text{mm}] = (\text{digital OUT} * \frac{1,02}{16368} - 0,01) * \text{MB} [\text{mm}]$$

Example: MB = 10 mm, digital value = 8184, measurement = 5 mm

Digital error codes are output like measurements.

The range of values for error codes: 16370 ... 16383 (digital OUT)

- |       |                         |       |   |
|-------|-------------------------|-------|---|
| 16370 | No object recognizable  | 16376 | Target cannot be evaluated              |
| 16372 | too close to the sensor | 16378 | external laser off                      |
| 16374 | too far from the sensor | 16380 | Trigger mode, pulses coming too quickly |

## 3000 Sensor State

### Object 3000h: Connection status

3000	RECORD	Sensor state	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Unsigned8	r
2	VAR	Sensor 2	x	Unsigned8	r

- x = 0 : No RS422 extension terminal
- x = 1 : Terminal starts synchronization phase
- x = 2 : Terminal in synchronization phase 1
- x = 3 : Terminal in synchronization phase 2
- x = 4 : Terminal in synchronization phase 3
- x = 5 : unknown type of sensor
- x = 6 : unknown baud rate
- x = 7 : Error during serial initialization
- x = 8 : Sensor timeout
- x = 16 : Sensor communication ok
- x = 17 : Measurement reception ok

## 5.2.8 ILD2200

### Overview of objects

Index (h)		Name	Description
Sensor 1	Sensor 2		
2005	4005	Sensor info	Sensor information (other)
2006	4006	Interface settings	Baud rate extension terminal
2050	4050	Get info	Query sensor information
2051	4051	Get settings	Selection of the sensor
2101	4101	Reset	Reboot sensor
2132	4132	Laser on	Switch on laser light source
2181	4181	Average	Averaging setting
21A0	41A0	Data on	Switch measurement output on/off
21E0	41E0	Zeroing	Setting masters and the mid-point
24A0	44A0	Key lock	Button lock
2999	4999	Sensor type	Specify sensor type
2FF0	4FF0	Measurement value	Reading out the measurements
3000		Sensor state	Connection status

For a description of the individual commands, also see Chapter "RS422 serial port" in the sensor instructions.

### 2005 Sensor info

#### Object 2005h: Sensor information

2005	RECORD	Sensor info	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	8	Unsigned8	r
1	VAR	Sensor name	ILD2200	String	r
2	VAR	Measuring range	20	String	r
3	VAR	Software version		String	r
4	VAR	Hardware version		String	r
5	VAR	Serial No.	01110576	String	r
6	VAR	Option no	0006	String	r
7	VAR	Calibration date		String	r
8	VAR	Article no		String	r

### 2006 Interface settings

#### Object 2006h: Baud rate extension terminal

2006	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	5	Unsigned8	r
1	VAR	Baud rate	691200	Unsigned32	rw

The baud rate in object 2006:01 determines the baud rate of the RS422 extension terminal. The baud rate of the sensor is defined in object 21B0: 02. The two baud rates must match.

**2050 Get Info****Object 2050h: Query sensor information**

2050	RECORD	Get info	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to retrieve the infostring from the sensor.

**2051 Get settings****Object 2051h: Query sensor settings**

2051	RECORD	Get settings	Value/parameter	Data type	Access
				Boolean	w

Causes the Terminal to send the GetSettings command to the sensor and to store the received sensor settings in the 2005h objects.

**2101 Reset****Object 2101h: Initialize sensor (boot)**

2101	RECORD	Reset	Value/parameter	Data type	Access
				Boolean	w

**2132 Laser On****Object 2132h: Switch on laser light source**

2132	RECORD	Laser on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Laser off

x = 1 : Laser on.

**2181 Average****Object 2181h: Averaging**

2181	RECORD	Average	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Average type	x	Int16	rw
2	VAR	Number of values	y	Int16	rw

x = 0 : recursive average      Recursive average of 1 to 32768 measurements

x = 1 : moving average      moving average of 1 to 128 measurements

x = 2 : Median      median of 3, 5, 7 or 9 measurements

The averaging number applies only for the moving and the recursive average.

Averaging number	1	2	4	8	16	32	64	128	256	512	1024	2048	4096
y	0	1	2	3	4	5	6	7	8	9	10	11	12
Averaging number	8192	16384	32768										
y	13	14	15										

**21A0 Data On****Object 21A0h: Switch measurement output on/off**

21A0	RECORD	Data on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Data output off

x = 1 : Data output on

**21E0 zeroing, mastering****Object 21E0h: Zeroing, mastering/**

21E0	RECORD	Zeroing, mastering	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	4	Unsigned8	r
1	VAR	Reserved			
2	VAR	Master value		Int16	rw
3	VAR	Zeroing/mastering active	x	Boolean	r
4	VAR	Mastering/reset mastering	y	Boolean	w

x = 0 : Setting of masters and mid-point cancelled

x = 1 : Masters/mid-point set

y = 0 : Cancel setting of masters and mid-point

y = 1 : Setting masters and the mid-point

**24A0 Key Lock****Object 24A0h: Button lock**

24A0	RECORD	Key lock	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Unlock keyboard

x = 1 : Keyboard locked

**2999 Sensor Type****Object 2999h: Specify sensor type**

2999	RECORD	Sensor type	Value/parameter	Data type	Access
			ILD2200	String	rw

**2FF0 Measurement Value****Object 2FF0h: Reading out the measurements**

2FF0	RECORD	Measured value	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	1	Unsigned8	r
1	VAR	Measurement sensor 1		Unsigned16	r

The output values are issued as unsigned digital values (raw values).

Digital value	Use
0 ... 642	Reserve measuring range start
643 ... 64876	Measurement range
64877 ... 65519	Reserve measuring range end
65520 ... 65535	Error codes

Calculation of a measurement  
(in mm) from the digital value,  
reference value mid-point of  
measuring range

$$x [\text{mm}] = \left( \text{digital}_{\text{OUT}} * \frac{1,02}{65520} - 0,51 \right) * \text{Messbereich} [\text{mm}]$$

Example: MB = 10 mm, digital value = 643, measurement = -4.99989 mm

Digital error codes are output like measurements.

The range of values for error codes: 65520 ... 65535 ( $\text{digital}_{\text{OUT}}$ )

65522	No object recognizable
65524	too close to the sensor
65526	too far from the sensor

65528	Target cannot be evaluated
65530	external laser off

**3000 Sensor State****Object 3000h: Connection status**

3000	RECORD	Sensor state	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Unsigned8	r
2	VAR	Sensor 2	x	Unsigned8	r

- x = 0 : No RS422 extension terminal  
x = 1 : Terminal starts synchronization phase  
x = 2 : Terminal in synchronization phase 1  
x = 3 : Terminal in synchronization phase 2  
x = 4 : Terminal in synchronization phase 3  
x = 5 : unknown type of sensor  
x = 6 : unknown baud rate  
x = 7 : Error during serial initialization  
x = 8 : Sensor timeout  
x = 16 : Sensor communication ok  
x = 17 : Measurement reception ok

**5.2.9 ILD2300****3010 Laser On****Object 3010h: Switch on laser light source**

3010	RECORD	Laser On	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Boolean	rw
2	VAR	Sensor 2	y	Boolean	rw

x, y = 0 : Laser off

x, y = 1 : Laser on

Activates the laser with EtherCAT sensors connected.

### 5.2.10 ODC2500

**i** The optoCONTROL 2500 is shipped ex works with RS232 as active interface.

- Before using the RS422 extension terminal for the very first time, switch the interface in the optoCONTROL 2500 to RS422.
- Start the TwinCAT Manager
- In the Actions menu, select the command: Reload the configuration.
- Select object 2006:01 and set the baud rate to 691200.
- Select object 2999 sensor type and set the sensor used to ODC2500.

#### Overview of objects

Index (h)		Name	Description
Sensor 1	Sensor 2		
2005	4005	Sensor info	Sensor information (other)
2006	4006	Interface settings	Baud rate extension terminal
2050	4050	Get info	Query controller information
2101	4101	Reset	Reboot sensor
2154	4154	measuring program	Change measuring program
2155	4155	Switch edge	Change the edge
21A0	41A0	Data on	Switch measurement output on/off
2600	4600	Edit option data	Write options data in RAM
2601	4601	Edit program data	Measuring program data in RAM
2604	4604	Save option data	Save options data in Flash
2605	4605	Save program data	Save measuring program data in Flash
2606	4606	Read statistic	Read min - max values
2607	4607	Reset statistic	Read min - max values with reset
2999	4999	Sensor type	Specify sensor type
2FF0	4FF0	Measurement value	Reading out the measurements
3000		Sensor state	Connection status

For a description of the individual commands, see also the instructions for the Controller in Chapter

#### 2005 Controller-Info

##### Object 2005h: Sensor information

2005	RECORD	Sensor info	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	8	Unsigned8	r
1	VAR	Sensor name	ODC2500	String	r
2	VAR	Measuring range	34	String	r
3	VAR	Software version	1021	String	r
4	VAR	Hardware version		String	r
5	VAR	Serial No.	1011423	String	r
6	VAR	Option no	0	String	r
7	VAR	Calibration date		String	r
8	VAR	Article no		String	r

## 2006 Interface settings

### Object 2006h: Baud rate extension terminal

2006	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	5	Unsigned8	r
1	VAR	Baud rate	691200	Unsigned32	rw

The baud rate in object 2006:01 determines the baud rate of the RS422 extension terminal.

## 2050 Get Info

### Object 2050h: Query controller information

2050	RECORD	Get info	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to retrieve the infostring from the controller.

## 2101 Reset

### Object 2101h: Initialize controller (boot)

2101	RECORD	Reset	Value/parameter	Data type	Access
				Boolean	w

## 2154 Measuring Program

### Object 2154h: Selection of measuring program

2154	RECORD	measuring program	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : EDGEHL  
 x = 1 : EDGELH  
 x = 2 : DIA  
 x = 3 : GAP  
 x = 4 : SEG\_2\_4

x = 5 : 2-SEG  
 x = 6 : USER1  
 x = 7 : USER2<sup>1</sup>  
 x = 8 : USER3<sup>1</sup>  
 x = 9 : USER4<sup>1</sup>

1) Presupposes that appropriate programs are installed in the controller.

## 2155 Switch Edge

### Objekt 2155h: Change the edge

2155	RECORD	Switch edge	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	4	Unsigned8	r
1	VAR	Front edge 1	x	Unsigned16	rw
2	VAR	Front edge 2	x	Unsigned16	rw
3	VAR	Rear edge 1	x	Unsigned16	rw
4	VAR	Rear edge 2	x	Unsigned16	rw

x = 0 ... 80

## 21A0 Data On

### Object 21A0h: Switch measurement output on/off

21A0	RECORD	Data on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Data output off  
 x = 1 : Data output on

**2600 Edit option data****Object 2600h: Write options data in RAM**

2600	RECORD	Edit option data	Value/parameter	Data type	Access
				Int8[44]	w

For a description of the command, see also the instructions for the Controller in Chapter "Commands".

**2601 Edit program data****Object 2601h: Write measuring program data RAM**

2601	RECORD	Edit program data	Value/parameter	Data type	Access
				Int8[82]	w

For a description of the command, see also the instructions for the Controller in Chapter "Commands".

**2604 Save option data****Object 2604h: Save options data in Flash**

2604	RECORD	Save option data	Value/parameter	Data type	Access
				Boolean	w

For a description of the command, see also the instructions for the Controller in Chapter "Commands".

**2605 Save program data****Object 2605h: Save measuring program data in Flash**

2605	RECORD	Edit measuring program	Value/parameter	Data type	Access
				Boolean	w

For a description of the command, see also the instructions for the Controller in Chapter "Commands".

**2606 Read Statistic****Object 2606h: Read min - max values**

2606	RECORD	Read statistic	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Min value		Int32	rw
2	VAR	Max value		Int32	rw

$$\text{Min/Max[mm]} = \text{Min/Max[0...65519]} * 40.824 / 65519 - 0.4204872$$

The optoCONTROL 2500 provides a min value and a max value to the object.

**2607 Reset Statistic****Object 2607h: Read min-max values, statistics in the sensor are reset**

2607	RECORD	Reset statistic	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Min value		Int32	rw
2	VAR	Max value		Int32	rw

$$\text{Min/Max[mm]} = \text{Min/Max[0...65519]} * 40.824 / 65519 - 0.4204872$$

The optoCONTROL 2500 provides a min value and a max value to the object. Then the memory for the min value and the max value is set to zero in the optoCONTROL 2500.

**2999 Sensor Type****Object 2999h: Specify sensor type**

2999	RECORD	Sensor type	Value/parameter	Data type	Access
			ODC2500	String	rw

**2FF0 Measurement Value****Object 2FF0h: Read out the measurements**

2FF0	RECORD	Measured value	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	1	Unsigned8	r
1	VAR	Measurement sensor 1		Unsigned16	r

Calculation of a measurement (in mm)  
from the digital value

$$x \text{ [mm]} = \text{digital OUT} * \frac{34,4386}{65519} - 0,2221$$

Digital error codes are output like measurements.

- 65521 No flank
- 65522 At the beginning of the image
- 65523 At the end of the image
- 65524 Dark-light flank
- 65525 Light-dark flank
- 65526 Min. number of flanks
- 65527 Maximum number of flanks
- 65528 No valid measuring program
- 65529 Segment 1st edge > = 2nd edge
- 65530 Segment number of edges < last edge
- 65531 No valid measurement distance
- 65533 Laser switched off
- 65534 No valid float number
- 65535 DMA Setup error

**3000 Sensor State****Object 3000h: Connection status**

3000	RECORD	Sensor state	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Unsigned8	r
2	VAR	Sensor 2	x	Unsigned8	r

- x = 0 : No RS422 extension terminal
- x = 1 : Terminal starts synchronization phase
- x = 2 : Terminal in synchronization phase 1
- x = 3 : Terminal in synchronization phase 2
- x = 4 : Terminal in synchronization phase 3
- x = 5 : unknown type of sensor
- x = 6 : unknown baud rate
- x = 7 : Error during serial initialization
- x = 8 : Sensor timeout
- x = 16 : Sensor communication ok
- x = 17 : Measurement reception ok

### 5.2.11 ODC2600

**i** The optoCONTROL 2600 is shipped ex works with RS232 as active interface.

- Before using the RS422 extension terminal for the very first time, switch the interface in the optoCONTROL 2600 to RS422.
- Start the TwinCAT Manager
- In the Actions menu, select the command: Reload the configuration.
- Select object 2006:01 and set the baud rate to 691200.
- Select the Object 2999 sensor type and set the sensor used to ODC 2600.

#### Overview of objects

Index (h)		Name	Description
Sensor 1	Sensor 2		
2005	4005	Sensor info	Sensor information (other)
2006	4006	Interface settings	Baud rate extension terminal
2050	4050	Get info	Query controller information
2101	4101	Reset	Reboot sensor
2130	4132	Set light tuning	Flexible edge detection threshold
2154	4154	measuring program	Change measuring program
2155	4155	Switch edge	Change the edge
21A0	41A0	Data on	Switch measurement output on/off
2401	4401	Trigger mode reset	Stop triggering
2402	4402	trigger mode trigger	Enable trigger-controlled output
2600	4600	Edit option data	Write options data in RAM
2601	4601	Edit program data	Measuring program data in RAM
2604	4604	Save option data	Save options data in Flash
2605	4605	Save program data	Save measuring program data in Flash
2606	4606	Read statistic	Read min - max values
2607	4607	Reset statistic	Read min - max values with reset
2999	4999	Sensor type	Specify sensor type
2FF0	4FF0	Measurement value	Reading out the measurements
3000		Sensor state	Connection status

For a description of the individual commands, see also the instructions for the Controller in Chapter "Control commands".

#### 2005 Controller-Info

##### Object 2005h: Sensor information

2005	RECORD	Sensor info	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	8	Unsigned8	r
1	VAR	Sensor name	ODC2600	String	r
2	VAR	Measuring range	40	String	r
3	VAR	Software version	1013	String	r
4	VAR	Hardware version		String	r
5	VAR	Serial No.	0311050	String	r
6	VAR	Option no	0	String	r
7	VAR	Calibration date		String	r
8	VAR	Article no	4321004	String	r

## 2006 Interface settings

### Object 2006h: Baud rate extension terminal

2006	RECORD	Interface settings	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	5	Unsigned8	r
1	VAR	Baud rate	691200	Unsigned32	rw

The baud rate in object 2006:01 determines the baud rate of the RS422 extension terminal.

## 2050 Get Info

### Object 2050h: Query controller information

2050	RECORD	Get info	Value/parameter	Data type	Access
				Boolean	w

Causes the terminal to retrieve the infostring from the controller.

## 2101 Reset

### Object 2101h: Initialize controller (boot)

2101	RECORD	Reset	Value/parameter	Data type	Access
				Boolean	w

## 2130 Set Light Tuning

### Object 2130h: Light reference for flexible edge detection threshold

2130	RECORD	Set light tuning	Value/parameter	Data type	Access
			x	Boolean	w

x = 0 : Reset light reference, i.e. solid edge detection threshold

x = 1 : Activates light reference for flexible edge detection threshold

## 2154 Measuring Program

### Object 2154h: Selection of measuring program

2154	RECORD	Measuring program	Value/parameter	Data type	Access
			x	Int8	rw

x = 0 : EDGEHL

x = 5 : MULTISEG

x = 1 : EDGELH

x = 6 : USER1

x = 2 : DIA

x = 7 : USER2<sup>1</sup>

x = 3 : GAP

x = 8 : USER3<sup>1</sup>

x = 4 : SEG\_2\_4

x = 9 : USER4<sup>1</sup>

1) Presuppose that appropriate programs are installed in the controller.

## 2155 Switch Edge

### Objekt 2155h: Change the edge

2155	RECORD	Switch edge	Value/parameter	Data type	Access
Sub-indices					

0	VAR	Number of entries	4	Unsigned8	r
1	VAR	Front edge 1	x	Unsigned16	rw
2	VAR	Front edge 2	x	Unsigned16	rw
3	VAR	Rear edge 1	x	Unsigned16	rw
4	VAR	Rear edge 2	x	Unsigned16	rw

x = 0 ... 80

**21A0 Data On****Object 21A0h: Switch measurement output on/off**

21A0	RECORD	Data on	Value/parameter	Data type	Access
			x	Boolean	rw

x = 0 : Data output off

x = 1 : Data output on

**2401 Trigger mode reset****Object 2401h: Stop triggering**

2401	RECORD	Trigger mode reset	Value/parameter	Data type	Access
				Boolean	w

**2402 Trigger Mode Trigger****Object 2402h: Start triggering**

2402	RECORD	Trigger mode trigger	Value/parameter	Data type	Access
				Boolean	w

**2600 Edit option data****Object 2600h: Write options data in RAM**

2600	RECORD	Edit option data	Value/parameter	Data type	Access
				Int8[44]	w

For a description of the command, see also the instructions for the Controller in Chapter "Control Commands".

**2601 Edit program data****Object 2601h: Write measuring program data in RAM**

2601	RECORD	Edit program data	Value/parameter	Data type	Access
				Int8[82]	w

For a description of the command, see also the instructions for the Controller in Chapter "Control Commands".

**2604 Save option data****Object 2604h: Save options data in Flash**

2604	RECORD	Save option data	Value/parameter	Data type	Access
				Boolean	w

For a description of the command, see also the instructions for the Controller in Chapter "Control Commands".

**2605 Save program data****Object 2605h: Save measuring program data in Flash**

2605	RECORD	Edit measuring program	Value/parameter	Data type	Access
				Boolean	w

For a description of the command, see also the instructions for the Controller in Chapter "Control Commands".

**2606 Read Statistic****Object 2606h: Read min - max values**

2606	RECORD	Read statistic	Value/parameter	Data type	Access
				Boolean	w

**Sub-indices**

0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Min value		Int32	rw
2	VAR	Max value		Int32	rw

Min/Max[mm] = Min/Max[0...65519] \* 40.824 / 65519 - 0.4204872

The optoCONTROL 2600 provides a min value and a max value to the object.

## 2607 Reset Statistic

### Object 2607h: Read min-max values, statistics in the sensor are reset

2607	RECORD	Reset statistic	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Min value		Int32	rw
2	VAR	Max value		Int32	rw

$$\text{Min/Max[mm]} = \text{Min/Max}[0...65519] * 40.824 / 65519 - 0.4204872$$

The optoCONTROL 2600 provides a min value and a max value to the object. Then the memory for the min value and the max value is set to zero in the optoCONTROL 2600.

## 2999 Sensor Type

### Object 2999h: Specify sensor type

2999	RECORD	Sensor type	Value/parameter	Data type	Access
			ODC2600	String	rw

## 2FF0 Measurement Value

### Object 2FF0h: Read out the measurements

2FF0	RECORD	Measured value	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	1	Unsigned8	r
1	VAR	Measurement sensor 1		Unsigned16	r

Calculation of a measurement (in mm)  
from the digital value

$$x [\text{mm}] = \text{digital OUT} * \frac{40,824}{65519} - 0,4204872$$

Digital error codes are output like measurements.

65521	No flank	65528	No valid measuring program
65522	At the beginning of the image	65529	Segment 1st edge > = 2nd edge
65523	At the end of the image	65530	Segment number of edges < last edge
65524	Dark-light flank	65531	No valid measurement distance
65525	Light-dark flank	65533	Laser switched off
65526	Min. number of flanks	65534	No valid float number
65527	Maximum number of flanks	65535	DMA Setup error

## 3000 Sensor State

### Object 3000h: Connection status

3000	RECORD	Sensor state	Value/parameter	Data type	Access
Sub-indices					
0	VAR	Number of entries	2	Unsigned8	r
1	VAR	Sensor 1	x	Unsigned8	r
2	VAR	Sensor 2	x	Unsigned8	r

- x = 0 : No RS422 extension terminal
- x = 1 : Terminal starts synchronization phase
- x = 2 : Terminal in synchronization phase 1
- x = 3 : Terminal in synchronization phase 2
- x = 4 : Terminal in synchronization phase 3
- x = 5 : unknown type of sensor
- x = 6 : unknown baud rate
- x = 7 : Error during serial initialization
- x = 8 : Sensor timeout
- x = 16 : Sensor communication ok
- x = 17 : Measurement reception ok

## 6. Synchronize Sensors

### 6.1 Introduction

The synchronization of connected sensors/controller among each other in the EtherCAT is realized via the Distributed Clock.

With it it is not necessary or possible to transmit the synchronous signals via the synchronous input or output of the sensor respectively of the controller.

Unlike the Ethernet the synchronization does not occur via external signals but about the clocks in the controllers. Using the EtherCAT this results in the synchronous modes

- Synchronization off (= Free Run) and
- Synchronization on (= DC-Sychron).

### 6.2 Simultaneous Synchronization


The following description explains the synchronization of two laser-optical optoNCDT 1700 displacement sensors.

- ➡ Connect both sensors to be synchronized to the RS422 extension terminal.
- ➡ Connect the EtherCAT coupler to a PC via a direct Ethernet connection (LAN) or Switch (Intranet). Use a LAN cable with RJ-45 connectors.
- ➡ Start the TwinCAT® System Manager program.


The RS422 extension terminal and the sensors are configured, see Chap. 5.1.4.

- ➡ In the TwinCAT menu, select the Reset TwinCAT (Config Mode) command.


- ➡ Click on PLC with the right mouse button in the System – Configuration. Select Add New Item.




- ➡ Select Standard PLC Project and rename the project in the field Name.



- ➡ Click twice on MAIN (PRG) and start the editor.
- ➡ Add the variable Dist with the syntax Dist AT %I\* : INT;.
- ➡ Add the variable Dist\_1 with the syntax Dist\_1 AT %I\* : INT;.




- ➡ Change to the Build menu and select the item Build Sync1700.




Link the Dist input with the variable Dist.

- ➡ Click on TxPDO1 > Dist with the right mouse button in the system configuration and select Change Link.




- ➡ Select the MAIN. Dist > IB xxxxxxx.0, INT [2.0] item and quit with OK.



Link the Dist\_1 input with the variable Dist\_1.

► Click on TxPDO1 > Dist\_1 with the right mouse button in the system configuration and select Change Link.

► Select the MAIN. Dist\_1 > IB xxxxxxxx.0, INT [2.0] item and quit with OK.




In the example, the ILD1700 operates with a measuring rate of 1.25 kHz. Using object 2250:2, the measuring rate can be changed if necessary, see Chap. 5.2.7. For synchronization, the sensor measuring rate and the synchronization rate or cycle time of the extension terminal must be compatible.


Measuring rate [kHz]	Cycle time [μs]	The cycle time of the PLC tasks should also correspond to the SYNC0 cycle time or a multiple of it.
2.5	400	
1.25	800	
0.625	1600	
0.3125	3200	

Change the Base Time of the tasks.

- Double click on Real-Time and switch to the Settings tab.
- Choose a base time of 200 μs.



- Click twice on PlcTask and activate the Auto-start function.
- Set the synchronous time on 0.8 ms in the Cycle ticks field.



- ➡ Select the RS422 extension terminal. Go to the DC tab and select DC-Synchron as operation mode.
- ➡ Click the Advanced Settings button.
- ➡ Enter the cycle time of the synchron pulses, e. g. 800 µs for an ILD1700 with a measuring rate of 1.25 kHz.




Fig. 9 Cycle time for a simultaneous synchronization

Activate the Configuration.

- ➡ Change to the TwinCAT menu and select Activate Configuration.

### 6.3 Alternating Synchronization

- With this type of synchronization, the two sensors measure alternately and it is intended e.g. for thickness measurement of transparent objects or a difference measurement on closely spaced measuring points.
- Not all sensor models are suitable for alternating synchronization. The output rate of a sensor with alternating synchronization is halved; the total measuring rate is equal to the set measuring rate of one sensor.


The following description explains the alternating synchronization of two laser-optical optoNCDT 1700 displacement sensors.

- ➡ Connect both sensors to be synchronized each at their own RS422 extension terminal.
- ➡ Connect the EtherCAT coupler to a PC via a direct Ethernet connection (LAN) or Switch (Intranet). Use a LAN cable with RJ-45 connectors.
- ➡ Start the TwinCAT® System Manager program.


The RS422 extension terminals and the sensors are configured, see Chap. 5.1.4.

- ➡ In the TwinCAT menu, select the Reset TwinCAT (Config Mode) command.


- ➡ Click on PLC with the right mouse button in the System Configuration. Select Add New Item.




- ➡ Select Standard PLC Project and rename the project in the field Name.
- ➡ Confirm the entry with Add.



- ➡ Click twice on MAIN (PRG) and start the editor.
- ➡ Add the variable Dist\_2 with the syntax Dist\_2 AT %I\* : INT;.
- ➡ Add the variable Dist\_3 with the syntax Dist\_3 AT %I\* : INT;.




- ➡ Change to the Build menu and select the item Build Sync1700.




Link the Dist input of Term 2 with the variable Dist\_2.

- ➡ Click on TxPDO1 > Dist with the right mouse button in the system configuration and select Change Link.




- Select the MAIN. Dist\_2 > IB xxxxxx.0, INT [2.0] item and quit with OK.



Link the Dist input of Term 3 with the variable Dist\_3.

- Click on TxPDO1 > Dist with the right mouse button in the system configuration and select Change Link.

- Select the MAIN. Dist\_3 > IB xxxxxx.0, INT [2.0] item and quit with OK.




In the example, the ILD1700 operates with a measuring rate of 2.5 kHz. Using object 2250:2, the measuring rate can be changed if necessary, see Chap. 5.2.7. For synchronization, the synchronization rate or cycle time of the extension terminal must be half the sensor measuring rate.


Measuring rate [kHz] sensor	Cycle time [μs] extension terminal	The cycle time of the PLC tasks should also correspond to the SYNC0 cycle time or a multiple of it.
2.5	800	
1.25	1600	
0.625	3200	
0.3125	6400	

Change the Base Time of the tasks.


- Double click on Real-Time and switch to the Settings tab.  
► Choose a base time of 200 μs.



- ➡ Click twice on PlcTask and activate the Auto-start function.
- ➡ Set the synchronous time on 0.8 ms in the Cycle ticks field.



- ➡ Select the Term 2 (CSP2008 Erweiterungsklemme.... Go to the DC tab and select DC-Synchron as operation mode.
- ➡ Click the Advanced Settings button.
- ➡ Enter the cycle time of the synchron pulses, e.g. 800 µs for an ILD1700 with a measuring rate of 2.5 kHz.



- ➡ Select the Term 3 (CSP2008 Erweiterungsklemme.... Go to the DC tab and select DC-Synchron as operation mode.
- ➡ Click the Advanced Settings button.
- ➡ Enter the cycle time of the synchron pulses, e. g. 800  $\mu$ s for an ILD1700 with a measuring rate of 2.5 kHz. Set the shift time to 400  $\mu$ s.




Fig. 10 Cycle time and shift time for an alternating synchronization

Activate the Configuration.

- ➡ Change to the TwinCAT menu and select Activate Configuration.

The following set shows the time shift for alternating synchronization using an ILD1700 with different measuring rates.

Measuring rate individual sensor	Output rate individual sensor	SYNC0 Cycle Time	+SYNC0 Cycle	
2.5 kHz	1.25 kHz	800 $\mu$ s	/2	400 $\mu$ s
1.25 kHz	0.6255 kHz	1600 $\mu$ s	/2	800 $\mu$ s
0.625 kHz	0.31255 kHz	3200 $\mu$ s	/2	1600 $\mu$ s
0.3125 kHz	0.156255 kHz	6400 $\mu$ s	/2	3200 $\mu$ s

Fig. 11 Time shift ILD1700 with alternating synchronization

## 7. Loading Project in Terminal, Saving

The following chapter describes how to save a project and to load it in the RS422 extension terminal(s).

This examples is based on the project of alternating synchronization, see Chap. 6.3.


Requirements:

- Both sensors to be synchronized are respectively connected to their specific RS244 extension terminal.
- The EtherCAT coupler is connected with a PC via a direct Ethernet connection (LAN) or Switch (Intranet).
- The TwinCAT® System Manager program runs with the alternating synchronization project, see Chap. 6.3.
- The extension terminals and sensors are configured, see Chap. 5.1.4.

The status of the objects 2006h, 2999h and 2132h is volatile. As long as you do not switch off the RS422 extension terminal(s), the settings are retained after a restart of the TwinCAT Manager.

You can instruct the TwinCAT Manager to set these objects automatically to the desired values.

- Choose the **Restart TwinCAT (Config Mode)** command in the TwinCAT menu.
- Double-click on the **Term 2 (CSP2008 extension terminal RS422 V2)** entry and switch to the programming environment in the **Startup** tab and click on the **New...** button.
- Choose the **2006:01** object and set the baud rate for your sensor. The ILD1700 operates using a baud rate of 115200 bauds. Confirm the dialogs with **OK**.



Repeat these steps for the sensor type (Object 2999h) and the laser light source (object 2132h).

- Click the New... button and choose object 2999h.

Transition	Protocol	Index	Data	Comment
C <PS>	CoE	0x1C12:00	0x00 (0)	clear sm pdos
C <PS>	CoE	0x1C13:00	0x00 (0)	clear sm pdos
C <PS>	CoE	0x1C13:01	0x1A00 (6656)	download pdo
C <PS>	CoE	0x1C13:00	0x01 (1)	download pdo
C PS	CoE	0x2006:01	0x0001C200 (115200)	Baud rate

Move Up    Move Down    New...    Delete...

The data type for the sensor is a string. However, in object 2999h it can be deposited only as hexadecimal value.

String „ILD1700“

Hex- value: 49 4c 44 31 37 30 30  
00




Fig. 12 Dialog for the transition of the sensor type into object 2999h

- Add the startup entry for the laser light source, object 2132h.

Transition	Protocol	Index	Data	Comment
C <PS>	CoE	0x1C12:00	0x00 (0)	clear sm pdos (0x1C12)
C <PS>	CoE	0x1C13:00	0x00 (0)	clear sm pdos (0x1C13)
C <PS>	CoE	0x1C13:01	0x1A00 (6656)	download pdo 0x1C13:01 i...
C <PS>	CoE	0x1C13:00	0x01 (1)	download pdo 0x1C13 count
C PS	CoE	0x2006:01	0x0001C200 (115200)	Baud rate
C PS	CoE	0x2999:00	49 4c 44 31 37 30 30	Sensor type
C PS	CoE	0x2132:00	0x01 (1)	Laser on

Move Up    Move Down    New...    Delete...    Edit...

Fig. 13 Startup entries for sensor configuration

- Add the three startup entries also in terminal Term 3 (CSP2008 extension terminal RS422 V2).


Activate the configuration.

- Switch to the TwinCAT menu and choose the Activate Configuration entry.

Save the configuration

- Switch to the system configuration and mark Solution 'T1700' (x xx) at the beginning of the tree.

- Choose the Save T1700.sln entry in the File menu to save the project.



## 8. Warranty

All components of the device have been checked and tested for functionality at the factory. However, if defects occur despite our careful quality control, MICRO-EPSILON or your dealer must be notified immediately.

The liability for material defects is 12 months from delivery. Within this period, defective parts, except for wearing parts, will be repaired or replaced free of charge, if the device is returned to MICRO-EPSILON with shipping costs prepaid. Any damage that is caused by improper handling, the use of force or by repairs or modifications by third parties is not covered by the liability for material defects. Repairs are carried out exclusively by MICRO-EPSILON.

Further claims can not be made. Claims arising from the purchase contract remain unaffected. In particular, MICRO-EPSILON shall not be liable for any consequential, special, indirect or incidental damage. In the interest of further development, MICRO-EPSILON reserves the right to make design changes without notification.

For translations into other languages, the German version shall prevail.

## 9. Service, Repair

In the case of the RS422 extension terminal has a defect, please send the affected parts for repair or exchange. If the cause of a fault cannot be clearly identified, please send the entire measuring system to:

MICRO-EPSILON Optronic GmbH  
Lessingstraße 14  
01465 Langebrück, Germany  
Telephone: + 49 35201/729 - 0  
Fax: + 49 35201/729 - 90  
[optronic@micro-epsilon.de](mailto:optronic@micro-epsilon.de)  
[www.micro-epsilon.com](http://www.micro-epsilon.com)

## 10. Decommissioning and Disposal

- Disconnect all the cables on the RS422 extension terminal.  
Incorrect disposal may cause harm to the environment.
- Dispose of the device, its components and accessories, as well as the packaging materials in compliance with the applicable country-specific waste treatment and disposal regulations of the region of use.





MICRO-EPSILON MESSTECHNIK GmbH & Co. KG  
Königbacher Str. 15 · 94496 Ortenburg / Germany  
Tel. +49 (0) 8542 / 168-0 · Fax +49 (0) 8542 / 168-90  
[info@micro-epsilon.de](mailto:info@micro-epsilon.de) · [www.micro-epsilon.com](http://www.micro-epsilon.com)

X9751268-A041117HDR

© MICRO-EPSILON MESSTECHNIK

